





TMT

Assembly stands




Assembly table for pre-assembly of hardware and gaskets. Stable steel construction. Work table for all pre-assembly tasks for hardware and gaskets on windows and doors. Equipped with two clamps. Clamping device for profiles with a depth of 45 - 120 mm and facing width of 50 - 150 mm. Clamping position can be adjusted. Clamping cylinder is activated by a foot switch. 180° pivoting feature for the clamped profiles in 30° steps via a foot switch, lockable. Support arms for long parts. Two storage areas for setting down tools and small parts. Drawers for tools. Rack for screw driving unit or drill. 4-fold compressed air supply. Double two-pin grounded socket.




Clamping device

Clamping device for profiles with a depth of 45 - 120 mm and facing width of 50 - 150 mm. Clamping position adjustable in the longitudinal direction of the profile, clamping cylinder actuated via a foot switch




Pivoting mechanism

180° pivoting feature for the clamped profiles in 30° steps via a foot switch, lockable




Support arms

Support arms for long parts such as multiple locking hardware. Storage areas for tools and small parts




Storage area

Storage area with five trays. PVC containers for small accessories, hardware and screws



Drawer


Drawer for tools. Rubber coated tool trays



Maintenance unit

Maintenance unit for compressed-air tools






4-fold compressed air connection

4-fold compressed air connection for connecting compressed-air tools



Articulated foot

Working height can be set to 850 - 1,000 mm by means of adjustable feet



Tool rack

Tool rack for pneumatic or electric tools





MODELS

TMT 2000



DIMENSION AND WEIGHT

| | |
|-------------|-----------------------|
| Length (mm) | <input type="radio"/> |
| Width (mm) | <input type="radio"/> |
| Height (mm) | <input type="radio"/> |
| Weight (kg) | <input type="radio"/> |

CHARACTERISTICS

| | |
|--|----------------------------------|
| Clamps | <input type="radio"/> |
| Storage areas for setting down tools and small parts | <input type="radio"/> |
| Drawers for tools | <input checked="" type="radio"/> |
| Rack for screw driving unit or drill | <input checked="" type="radio"/> |
| 4-fold compressed air supply | <input checked="" type="radio"/> |
| Operating air pressure (bar) | <input type="radio"/> |
| Air consumption approx. (l/min) | <input type="radio"/> |
| Double two-pin grounded socket | <input checked="" type="radio"/> |

Included ● Available ○